



INSTRUCTIONS:

1. PART IS TO BE FREE OF CONTAMINATION (OVER CURE).
2. DEFLASH ALL PARTING LINES.
3. TRIM PER INSTRUCTIONS ON PAGE 2.
4. APPLY SPECIAL MARKINGS AS PER SALES ORDER.

DO NOT SCALE	DRAWN BY	 (402) 467-5221 <a href="http://www.snyder.net">www.snyder.net</a>	TITLE:	REVISION
STATUS:	SB		LID 2900 MONSTER CMBO STACK	A
© SNYDER INDUSTRIES INC., 2015		<small>           TOLERANCES UNLESS OTHERWISE SPECIFIED:            ANGULAR = ±1/2°            FRACTIONAL = ±1/16"            .X = 0.1", .XX = .03", .XXX = .005"         </small>	PART NO.	SHEET
			1017100M	1 OF 2
			ENG. ID.	
			1017100M	